



PA OFFICE: 1-800-346-8524

FAX : 1-717-944-7681

KY OFFICE: 1-800-296-9227

FAX: 1-270-586-4493

DARK LIQUID COMING FROM UNDERNEATH HORSECARPET®

Please do not be alarmed about the dark liquid coming from the HORSECARPET®. A sample was taken of a similar dark liquid from a playground, and we found it to be tannins washing off the wood fiber material. At times there will also be an oily sheen visible on the surface of the water. All living things contain some amount of oil, some more than others; such as corn versus wood. This minute amount of natural oil is associated with tannins. The liquid was tested and found to have a pH in the normal range of drinking water. The stain associated with this liquid will breakdown and bleach out in a period of time when sunlight is present, or will cease to exist after several rain storms. The dark liquid is externally harmless to humans and animals.

It is strongly recommended that a drainage system be installed under your HORSECARPET® footing and ported to a storm drain to prevent liquid inadvertent water run off from the equine footing system.

If you have any future problems, please call us at 1-800-346-8524.

THANK YOU!

Ted Illjes
Research & Development